

1. Following changes are made in the accounting due to non availability/Discrepancies of Main Meter readings.

| Sl.no | Date | Location | Feeder/ICT | Loc.ID& SEM Sl.no | Repalced LOC.ID& Sl.no | with SEM | Remarks |
|--------------|----------------------------|-----------------|---------------------------|------------------------------|-----------------------------------|-----------------|---------------------|
| 1 | 25.02.13 To 03.03.13 | Indore | 400KV Bina(PG) line | (MB-30) NP-2601-A | (MB-31) NP5760-A | | Data was corrupted. |
| 2 | 25.02.13 To 03.03.13 | Anuppur | 200kv Kotmikala line 1 | (MP-56) NP-2163-A | (CS-51) NP-2413-A | | Data not received. |
| 3 | 25.02.13 To 03.03.13 | Anuppur | 200kv Kotmikala line 2 | (MP-57) NP-4228-A | (CS-52) NP-2155-A | | Data not received. |
| 4 | 25.02.13 To 03.03.13 | Raipur | 400kV side of ICT-3 | (CS-19) NP-2325-A | (CS-20) NP-2101-A | | Data not received. |