



**Power System Operation Corporation Limited**  
**Western regional Load Despatch Centre**  
**FLASH REPORT**

**WRLDC/June-2016/GDI**

**Incident: TRIPPING OF 400kV BUS-2 AT KANSARI S/s(GEB)**

**1. Date and Time:29/06/2016 05:40Hrs**

**2. Antecedent Conditions**

**1. Frequency of NEW Grid/SR Grid**

Event	Frequency(Hz)	Time(hh:mm)
Pre incident	50	05:37
Post Incident	49.9	05:41

**2. Reason for Tripping:**Bus-2 tripping on fault at kansari S/s.

**3. Areas Affected By Disturbance:.** NIL

Generation loss: NIL

No critical loadings observed.

**4. Elements affected:**

Feeder	Tripping time (hh:mm)	Restoration time(hh:mm)	Remarks
400kV Bus-2 at KANSARI	05:40		BUS-2 FAULT AT KANSARI s/S.
400Kv KANSARI-KANKROLI-I	05:40		BUS-2 FAULT AT KANSARI s/S.
400Kv KANSARI-VADAVI-II	05:40		BUS-2 FAULT AT KANSARI s/S.
400Kv SOJA-KANSARI-I	05:40		BUS-2 FAULT AT KANSARI s/S.
400Kv VARSANA-KANSARI-S/C	05:40		BUS-2 FAULT AT KANSARI s/S.

400/220Kv KANSARI ICT-II	05:40	Restored.Time to be received	BUS-2 FAULT AT KANSARI s/S.
400/220Kv KANSARI ICT-III	05:40		Tripped on overload
400/220Kv KANSARI ICT-I	05:40	Restored.Time to be received	BUS-2 FAULT AT KANSARI s/S.

**5. Actions Taken:**

**LOAD IS NOT AFFECTED AS OTHER FEEDERS ARE IN SERVICE VIA BUS-1. Restoration is under process. Line loadings are normal.**

**6. Current Status: 400/220Kv ICT-1,ICT-2 AT KANSARI S/s is restored. Other feeders and ICTS RESTORATION IS UNDER PROGRESS.**

S.S.VELAYUTHAM

**(Shift Charge Manager)**