

1. Following changes are made in the accounting due to non availability/Discrepancies of Main Meter readings.

Sl.no	Date	Location	Feeder/ICT	Loc.ID& SEM Sl.no	Repalced LOC.ID& Sl.no	with SEM	Remarks
1	04.02.13 To 10.02.13	Indore	400KV Bina(PG) line	(MB-30) NP-2601-A	(MB-31) NP5760-A		Data was corrupted.
2	04.02.13 To 10.02.13	Chandrapur	400kV Bhadravati line-1	(MH-21) NP-2412-A	(MH-23) NP-2119-A		Data not received
3	04.02.13 To 10.02.13	RGPPPL	400kV Nagothane line 2	(RG-22) NP-6327-A	(RG-26) NP-6297-A		Erronious data recorded by SEM
4	04.02.13 To 10.02.13	Anuppur	200kv Kotmikala line 1	(MP-56) NP-2163-A	(CS-51) NP-2413-A		Data not received.
5	04.02.13 To 10.02.13	Anuppur	200kv Kotmikala line 2	(MP-57) NP-4228-A	(CS-52) NP-2155-A		Data not received.
6	04.02.13 To 10.02.13	Vapi	220kV KAPS line-2	(GU-65) NP-4181-A	(KA-24) NP-2280-A		Data not received.
7	07.02.13 To 08.02.13	Wardha	400KV Side of ICT-1	(MM-12) NP-6770-A	(MM-11) NP-6769-A		Data was corrupted.
8	07.02.13 To 08.02.13	Wardha	400KV Side of ICT-3	(MM-19) NP-6773-A	(MM-18) NP-6772-A		Data was corrupted.