

1. Following changes are made in the accounting due to non availability/Discrepancies of Main Meter readings.

Sl.no	Date	Location	Feeder/ICT	Loc.ID& SEM Sl.no	Repalced with LOC.ID& SEM Sl.no	Remarks
1	30.12.13 TO 05.01.14	Ujjain	220kV Kota line	(MP-54) NP-2138-A	(RS-01) NP-1067-B	Data not received.
2	30.12.13 TO 05.01.14	Ujjain	220kV Motak line	(MP-55) NP-2148-A	(RS-03) NP-1301-A	Data not received.
3	30.12.13 TO 05.01.14	Anuppur	200kv Kotmikala line 1	(MP-56) NP-2163-A	(CS-51) NP-2413-A	Data was corrupted.
4	03.01.14	VAPI	220KV side of ICT- 3	(GU-06)	(GU-05)	Data was corrupted.