

**FIRST INFORMATION REPORT ( 16.06.2017)**

<b>SN</b>	<b>Event Time</b>	<b>EVENT</b>	<b>Protection Acted</b>	<b>Equipment on BUS</b>	<b>REVIVAL</b>
1.	15:27 hr	BUS-5 & SATNA-3 line tripped. Satna-3 line R-phase jumper got snapped.	Zone-1 fault in Satna-3 line & LBB protection on Bus bar acted.	Satna-3 line on Bus-5	Bus-5 charged at 17:28 hr.  Satna-3 line U/P for jumper replacement.
2.		Satna-4 Line tripped.	Over Voltage protection.	Satna-4 line on Bus-6	Satna-4 line charged at 18:06 hr.
3.		HVDC-2 tripped.	Earth Fault protection.	HVDC-2 line on Bus-1.	Under checking.
4.		Unit-9 tripped.	400KV Elect Bus Bar Protection.	Unit-9 on Bus-5.	Unit Synchronised at 17:52 hr.

**Note:** At the time of event there was heavy rain & thundering in the region.